

## Vaisala HMP140 series humidity transmitters

<b>Output quantities:</b>	Relative humidity (%), temperature ( °C/°F )
<b>Current outputs:</b>	20...35 VDC, 17...24 VAC
<b>Analogue output signals: (scalable)</b>	0...20 mA, (4...20 mA), 0...1 V, 0...5 V, 0...10 V
<b>Screw terminals:</b>	0.5-1.5 mm <sup>2</sup> (AWG 15...20)

### Wiring diagram

The wiring can be done in either of the two ways shown below.

**mounting on a junction box**

**surface mount**

