


Vaisala HMW60U/Y humidity transmitter

Output quantities:	Relative humidity (%), temperature (°C/°F) in model HMW60Y
Operating voltage:	10...35 VDC ($R_L = 0 \Omega$) 20...35 VDC ($R_L = 500 \Omega$)
Output signal:	4...20 mA
Measurement range:	0...95 % RH
Measurement range:	-5...+55 °C
Screw terminals:	0.5...1.5 mm ²

Wiring diagram



Signal cables are connected to a removeable 5-pole screw connector.