

Triton Support Programs, Spare Parts Offering and Pricing – 2022

This document describes the Triton support programs and spare part offering for Triton for continuation of the product ramp down support phase through the year 2022. Pricing is effective January 1, 2022.

Triton Support Programs

January 1, 2022 – Prices are USD and both Prices and Listed Items are Subject to Change Without Notice

Overview

The Limited Support SkyServe program continues to be offered in 2022. This provides an inexpensive approach to maintaining your Triton hardware. Daily monitoring is NOT included for the Standard Triton.

The SkyServe Limited Support program includes:

- Online access to all your wind data
- Daily Back-up and Archiving of Data
- US Based Weekday, Technical support including email and phone
- Triton Observation Platform upgrades when available
- For Heater Tritons, the program includes heater burn monitoring during the winter, but other monitoring is customer's responsibility. There is no provision for running the heater system except through Vaisala.

Program Description

The SkyServe Limited Support program allows customers to monitor their fleet of Tritons and pay for field repairs as needed. Customers have the flexibility in carrying out field repairs. Either by contracting Vaisala, using their Vaisala Advanced Trained labor and parts, or using a Certified Triton Support Partner. Clients will continue to have access to Vaisala experts to help with remotely diagnosing issues with Triton hardware.

Table 1 shows the coverage details of services included in this program.

| Onsite Services | | |
|---|---------------------|--|
| | Limited Support | |
| Commissioning Reports (NOTE: Reports are included in the installation price if the Triton is moved/installed by Vaisala) | Included – see Note | |
| Field Repair Deployment (Vaisala or Certified Partners only) | Per Quote | |
| Advanced Field Repair Deployment (Vaisala Labor and Travel) | Per Quote | |
| Replacement Parts Expense | Per Quote | |
| Labor Expense | Per Quote | |
| Travel Expense | Per Quote | |
| Shipping, Expediting and Logistics Expense | Per Quote | |
| On-o | call Services | |
| | Limited Support | |
| Standard Phone/Email Support Weekdays (MST in the United States) 72-hour Weekday Response time | Included | |
| Advanced Technical Support Services (Triton troubleshooting) | Per Quote | |



| Data Analysis Support Services (Triton validation questions) | Per Quote | | |
|---|--|--|--|
| Customer installation support (Triton Siting questions) | Per Quote | | |
| Online and Remote Monitoring Services | | | |
| | Limited Support | | |
| Data Communications: - Choose satellite or cellular: | | | |
| NOTE: Customer is responsible for initiating the Globalstar, Inmarsat or 4G LTE subscription and paying the monthly communication fees associated with your Triton. | | | |
| Globalstar or Inmarsat communications service 4G LTE Cellular communications service | Not Included **(Customer Pays Direct to Provider) ** | | |
| Online Data Portal - 24/7 Access | Included | | |
| Daily Back-up and Archiving of data | Included | | |
| Winter 24/7 Remote Heater Operation (for Triton heater option only) | Optional | | |

Further details of the program can be found in the Limited Support SkyServe contract/proposal template, available on request from your Vaisala sales representatives.

Cost

Due to general cost increases, Triton support program pricing has been adjusted for 2022.

The cost of the program is:

- Limited Support Program for Standard or Heater Tritons: \$2,300 USD.
- Optional for Heater Tritons: 24/ 7 Remote Heater Operations during winter months for an additional \$3,450 USD per year.

Vaisala shall charge for applicable state or federal/national taxes as required in addition to the pricing referenced above. If you have tax exempt status, please share that with your Vaisala representative at the time of contract signing.

Triton Reactivation Fee

- Vaisala will charge a 5,000 USD reactivation fee (Vaisala part number 950-0019 SERVICES, Triton, Reactivation Fee) when a customer wishes to reconnect one of their existing Tritons for which a support contract was previously cancelled after receiving the ramp down notification in May 2019. The Triton reactivation fee is charged to recoup the expenses associated with reactivating the data service connection for a previously decommissioned Triton.
- Tritons that have been purchased second-hand, will not be supported under the Limited Support SkyServe contract.

Triton Spare Parts End-User Price List January 1, 2022 – Prices are USD and both Prices and Listed Items are Subject to Change Without Notice

This price list is provided as a reference for the offering Vaisala supports for Triton during the product ramp down support period until 31 December 2024. Some parts may be subject to limited availability, and once existing inventory is depleted, those parts will no longer be offered. The spare part offering pricing has been adjusted for 2022 to reflect the general cost increase and continued cost pressures brought about the effects of the Covid-19 pandemic on global supply chains.

Table 2 shows the Triton spare part offering and end-user pricing in USD (subject to change without notice).



| 240942 | OTS, MODEM Satellite, Inmarsat | 2472 |
|----------|---|------|
| 252533 | Triton Dual Modem Upgrade Assembly, North America (4G upgrade only) | 1875 |
| 252675 | Modem, LTE Cat 3 IP64 RV50 North America/Europe | 1397 |
| 253196 | Configured Modem, "North America/Europe" RV50 | 1748 |
| 253375 | Configured Modem, "APAC" RV50X | 1750 |
| 255069 | Triton Generic Cell Modem Upgrade Assembly | 780 |
| 680-0004 | KIT, Triton, GSP1720 Modem & MC-II Upgrade | 1663 |
| 415-0005 | OTS Modem, GSP-1720 | 1248 |
| 415-0010 | OTS, MODEM, GPS Receiver, USB Connection | 158 |
| 415-0014 | OTS Antenna, GSP-1720 | 1357 |
| 252145 | Antenna, Cellular Broadband Directional, N-female, IP67 | 254 |
| 241468 | TRIPOD, Inmarsat Antenna Tripod, Steel, Mast OD 1-5/8" | 117 |
| 244386 | Mounting Bracket Azimuth Canister Bracket for Pole | 208 |

| Item Code | 2. Triton - Spare Parts - Printed Circuit Boards | Price USD |
|-----------|--|-----------|
| 125-0001 | SWITCH, Contura Actuator Soft, Black | 68 |
| 510-0001 | PCBA, PC104DSP | 801 |
| 510-0016 | PCBA, Tested, Triton Heater Controller | 843 |
| 510-0025 | PCBA, Triton Peripheral Board | 936 |
| 510-0043 | PCBA, Tested, Triton Modem Carrier II | 306 |
| 610-0024 | ASSEM, Triton, Operator Panel | 1222 |
| 610-0037 | PCBA, Linux Board | 1749 |
| ASM211263 | Assembly, Triton Inmarsat Operator Panel | 1222 |

| Item Code | 3. Triton - Spare Parts - Power & Batteries | Price USD |
|-----------|--|-----------|
| 243646 | Solar Panel, 90W, 12V, 1209 x 537 x 50mm | 667 |
| 130-0002 | FUSE, 30Amp, Green, Blade Type, 12VDC, ATC | 65 |
| 130-0003 | FUSE, 5Amp, Tan, Blade Type, 12VDC, ATC | 65 |
| 130-0006 | FUSE, 20Amp, Yellow, Blade Type 12VDC ATO/ATC | 65 |
| 140-0187 | Cable, Power, Solar | 65 |
| 140-0188 | Cable, Power, Solar | 184 |
| 200-0010 | BRACE, Triton, Solar Panel, 9" Style | 134 |
| 405-0005 | OTS, BATTERY, 12V, 92AH 810 MCA, Group 27, AGM | 332 |
| 610-0056 | Assy, Triton Blue Sky / 247282 Programmed | 1559 |

| Item Code | 4. Triton - Spare Parts - Sensors & Peripherals | Price USD |
|-------------------|---|-----------|
| 490-0004 | OTS, Shield, RM Young | 180 |
| 610-0004 | Assy, Triton Heater, Pressure Transducer | 936 |
| 610-0023 | Assy, Triton Baro/RH & Orientation – NOTE: Very limited quantity available! | 3043 |
| TRITONAMBTEMP.FRU | Triton Field Support Kit Ambient Temp Sensor | 2317 |

| Item Code | 5. Triton - Spare Parts - Heater Parts | Price USD |
|-----------|--|-----------|
| 028-0004 | Sensor, Temperature (Used in Heater Panel) | 130 |
| 080-0001 | Heater Engine, Triton | 3125 |



| 125-0004 | Relay, 40A Automotive | 68 |
|------------------|---|------|
| 280-0001 | HOSE, Triton, Bottom, Heated Mirror | 275 |
| 410-0003 | OTS Pump, CM10 Mag Drive F | 279 |
| 610-0001 | Triton Heater Assembly | 4680 |
| 610-0005 | Triton Heater Panel | 9902 |
| TRITONHTRSEN.FRU | Triton Field Support Kit Heater Sensors | 3087 |

| Item Code | 6. Triton - Spare Parts - General Parts & Cables | Price USD |
|-----------|--|-----------|
| 241465 | Cable, Ethernet RJ45(M)-RJ45(M), CAT5E, UTP, PVC, 1.5m, Boot, BLK | 65 |
| 241466 | Cable, Ethernet RJ45(M)-RJ45(M), CAT5E, UTP, PVC, RED | 65 |
| 243951 | Triton G2 Speaker Tuned and Tested | 296 |
| 249338 | Triton FRU Standard Starter Kit | 10919 |
| 252531 | Cable, Coaxial SMA(M)-N(M), RG58C/U, 50ohm, 3.05m | 160 |
| 252672 | Formatted SD Card, Triton Linux Board | 180 |
| 025-0022 | CABLE, Cat5, 3 ft Long, White | 65 |
| 025-0023 | CABLE, Cat5, 3 ft Long, Green | 65 |
| 025-0024 | CABLE, Cat5, 15 ft Long, Orange | 65 |
| 025-0025 | CABLE, Cat5, 15 ft Long, Yellow | 65 |
| 025-0026 | CABLE, Cat5, 15 ft Long, Purple | 65 |
| 025-0027 | CABLE, Cat5, 15 ft Long, Blue | 65 |
| 025-0035 | CABLE ADAPTER DB9 - USB 1.1m black | 65 |
| 025-0038 | CABLE, Cat5, 10ft Long, Pink | 65 |
| 025-0068 | CABLE, 10ft, 12AWG, MC4 M-F Solar Cable Extensio | 65 |
| 025-0070 | CABLE, Cat5, 12 ft Long, Yellow | 65 |
| 025-0071 | CABLE, Cat5, 12 ft Long, Purple | 65 |
| 025-0072 | CABLE, Cat5, 12 ft Long, Blue | 65 |
| 060-0001 | Cable Assy, RF | 343 |
| 060-0002 | Cable Assy, RF | 283 |
| 060-0035 | CABLE ASSY, 64P Ribbon with Ferrite for Hex Array PC104 IF | 130 |
| 060-0036 | CABLE ASSY, 26P Ribbon Cable, 20", Rainbow, Hex Array Power Cable | 65 |
| 060-0037 | CABLE ASSY, 10P Ribbon Cable, 3", Hex Array Linux PB Serial Cable | 65 |
| 060-0038 | CABLE ASSY, 16P Ribbon Cable, 2", Hex Array Linux PB DIO Cable | 65 |
| 060-0040 | CABLE ASSY, Heater Controller Board Reset C | 65 |
| 060-0041 | CABLE ASSY, Pressure Sensor Cable | 65 |
| 060-0042 | CABLE ASSY, Triton Heater Panel, Relay Harness | 65 |
| 060-0043 | CABLE ASSY, Triton, GPRS Power Jumper Cable | 65 |
| 060-0048 | CABLE ASSY, 64P Ribbon Cable for Hex Array PC10 | 65 |
| 060-0056 | CABLE ASSY, Triton, Peripheral to DSP Power | 65 |
| 060-0057 | CABLE ASSY, 26P Ribbon Cable, 6", Triton Operat | 65 |
| 060-0059 | CABLE ASSY, Triton Heater Panel, Red Power Batt Lug Harness | 157 |
| 060-0060 | CABLE ASSY, Triton Heater Panel, Black Power Lug Harness | 271 |
| 060-0061 | CABLE ASSY, Triton Heater Panel, 43", Red Heater Power Cable | 65 |
| 060-0062 | CABLE ASSY, Triton Heater Panel, 44", Violet Feedback heater cable | 65 |
| 060-0065 | CABLE ASSY, Triton, 40P Cut Atapi Cable, DSP to | 65 |
| | | |



| 060-0075 | CABLE ASSY, Triton, Modem Carrier II to GSP1 | 190 |
|-------------------|--|-------|
| 060-0076 | CABLE ASSY, Triton, Cable Harness & Junction Box Assem | 1692 |
| 060-0080 | CABLE ASSY, Triton, Operator Panel Power Swi | 130 |
| 060-0082 | CABLE ASSY, Triton, Pos Batt Jumper, Red | 65 |
| 060-0083 | CABLE ASSY, Triton, Negative Battery Jumper, Black | 65 |
| 060-0086 | CABLE ASSY, Heater, Positive Power with Flag Connector | 65 |
| 060-0087 | CABLE ASSY, Heater, Negative Power with Ring | 65 |
| 060-0088 | CABLE ASSY, Heater, Signal with Ring Terminal | 65 |
| 060-0089 | CABLE ASSY, Heater, Switch Harness with Ring Terminals | 65 |
| 140-0042 | CONN, PLUG, Terminal Block, Vertical, 6 Pin | 65 |
| 140-0054 | CONN, Modular Adapter DB9 Female to RJ45 Female | 65 |
| 140-0056 | CONN, Housing, 2 Pos, Single Row, 0.100" Spaci | 65 |
| 140-0062 | CONN, CRIMP FEMALE TERMINAL Socket 22-24awg | 65 |
| 290-0004 | GASKET, Triton, Rear Door | 65 |
| 600-0005 | ASSEM, MECH, Triton Scupper Block | 604 |
| 610-0016 | ASSEM, Triton, Speaker Legacy (non-TPU) | 166 |
| 900-0037 | Triton Performance Upgrade Array (TPU) | 20253 |
| ASM211264 | Cable Assy, Inmarsat Power Jumper Cable | 68 |
| TRITONTPUSPKR.FRU | Triton Field Support Kit TPU Speakers, 6 Pieces | 2385 |